SouthernBiotech



SECTION 1: PRODUCT AND COMPANY IDENTIFICATION

GHS Product Identifier	Goat Fab Anti-Human IgG-AP
Other means of identification	N/A
Product type	Liquid
Product code	2041-04
Chemical formula	Not applicable
CAS No	Not applicable
SDS No.	2231533
Relevant Identified uses of the substance or mixture and uses	
advised against	Not applicable
Supplier's details	Southern Biotechnology Associates, Inc. 160 Oxmoor Boulevard Birmingham, Alabama 35209 USA Tel: (205) 945-1774 Fax: (205) 945-8768 Website: www.southernbiotech.com
Distributor and Emergency Phone No.	Refer to website for distributor and emergency phone numbers. Tel: (205) 945-1774

SECTION 2: HAZARDS IDENTIFICATION

Classification of the substance or mixture GHS-US classification Not classified

Label elements GHS-US labeling Hazard pictograms (GHS-US)

Hazard pictograms (GHS-US)	None required
Signal word (GHS-US)	None required
Hazard statements (GHS-US)	None required
Precautionary statements (GHS-US)	None required
Other hazards	Dilute azide-containing compounds in running water before discarding to avoid accumulation of potentially explosive deposits in lead or plumbing copper. Sodium azide is rapidly absorbed through skin.
Note	According to OSHA Hazard Communications Standard (CFR 1910.1200), if a mixture contains less than 1% hazardous chemical or less than 0.1% of a carcinogen, the mixture is not considered hazardous. However, precautions for handling potentially dangerous chemicals should be used when handling these products.
Unknown acute toxicity (GHS US)	No data available

Full text of H-phrases: see section 16

SECTION 3: COMPOSITION/INFORMATION ON INGREDIENTS

Substance/Mixture

Mixture

Other	Means	of	Identification

Not available

CAS Number	/other identifiers
0/10/110001	

CAS Number

Not applicable

Ingredient Name	Product Identifier	Percent	GHS Classification
Glycerol	(CAS No.) 56-81-5 / [EINECS(EC#)] 200-289-5	50	Not Classified
Sodium Azide	(CAS No.) 26628-22-8 / [EINECS(EC#)] 247-852-1	< 0.1	H300 H310 H400 H410

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section. See Section 16 for full text of GHS classifications.

SECTION 4: FIRST-AID MEASURES

Description of first aid measures

First-aid measures general First-aid measures after eye contact	Never give anything by mouth to an unconscious person. If you feel unwell, seek medical advice. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband. Immediately flush eyes with plenty of water, occasionally lifting the upper and
First-ald measures after eye contact	lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10 minutes. Get medical attention if irritation occurs.
First-aid measures after inhalation	Remove victim to fresh air and keep at rest in a position comfortable for breathing. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Get medical attention if adverse health effects persist or are severe. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.
First-aid measures after skin contact	Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur. Wash clothing before reuse. Clean shoes thoroughly before reuse.
First-aid measures after ingestion	Wash out mouth with water. Remove dentures if any. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Stop if the exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enter the lungs. Get medical attention. If necessary, call a poison center or physician.
Most important symptoms and effects, both acute and delayed	See Sections 2 and 11
Indication of immediate medical attention and special treatment needed, if necessary	Contains low levels of sodium azide. Medical conditions could be aggravated by exposure. None known or reported. Treat symptomatically.

Rev. 27-Aug-21

SECTION 5: FIRE-FIGHTING MEASURES

Suitable extinguishing media Unsuitable extinguishing media Special hazards arising from the substance or mixture

Hazardous thermal decomposition products Special protective actions for firefighters

Special protective equipment for firefighters

Use an extinguishing agent suitable for the surrounding fire. None known

In a fire or if heated, a pressure increase will occur and the container may burst.

No specific data

Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.

Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode

SECTION 6: ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

General measures: This product contains a material of biological origin. Use universal precautions during clean up procedures. Avoid breathing (vapor, mist). Use only in a well-ventilated area. Handle in accordance with good industrial hygiene and safety practice. Use personal protective equipment, see section 8.

For non-emergency personnel

No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk-through spilled material. Avoid breathing vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.

For emergency responders

If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non- emergency personnel".

Environmental precautions

Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).

Methods and material for containment and cleaning up

Small spill: Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Large spill: Stop leak if without risk. Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g., sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product.

Reference to other sections

See Section 1 for emergency contact information, Section 13 for waste disposal, and Section 8 for exposure controls and personal protection.

SECTION 7: HANDLING AND STORAGE

Precautions for safe handling

Precautions for safe handling: Put on appropriate personal protective equipment (see Section 8). Do not ingest. Avoid contact with eyes, skin and clothing. Avoid breathing vapor or mist. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse container.

Hygiene measures: Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed.

Goat Fab Anti-Human IgG-AP	SDS No. 2231533	Page 4 of 8
----------------------------	-----------------	-------------

Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Conditions for safe storage, including any incompatibilities

Technical measures: Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10). Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. Avoid strong oxidizers. Recommended storage temperature: 2 - 8°C

SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION

Control parameters

Sodium Azid	e (26628-22-8)	
USA NIOSH	NIOSH IDLH	Ceiling: 0.3 mg/m ³ NaN ₃
		Ceiling: 0.1 ppm HN ₃
USA OSHA	OSHA PEL (TWA)	Absorbed through skin
		(Vacated) Ceiling: 0.3 mg/m ³ NaN ₃
		(Vacated) Ceiling: 0.1 ppm HN ₃
ACGIH TLV	ACGIH TLV	Ceiling: 0.29 mg/ m ³ NaN ₃
		Ceiling: 0.11 ppm Hydrazoic acid vapor
Glycerol (56-	81-5)	
USA OSHA	OSHA PEL (TWA) (mg/m ³)	Respirable Fraction
		5 mg/m ³
USA OSHA	OSHA PEL (TWA) (mg/m ³)	Total Dust
		15 mg/m ³

Exposure controls General ventilation systems should be sufficient to control worker exposure to Appropriate engineering controls airborne contaminants; showers and evewash stations Environmental exposure controls Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Personal protective equipment Protective goggles, gloves Hand protection Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. Personal protective equipment for the body should be selected based on the Body protection task being performed and the risks involved and should be approved by a specialist before handling this product. Other skin protection Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. Tightly fitting safety goggles complying with an approved standard should be Eye protection used when a risk assessment indicates this is necessary to avoid exposure to Rev. 27-Aug-21

Goat Fab Anti-Human IgG-AP		SDS No. 2231533	Page 5 of 8
	liquid splashes, mists, gases or dus protection should be worn, unless protection: safety glasses with side	the assessment indicates a	•
Respiratory protection	Where risk assessment shows air-purifying respirators are appropriate use a full-face respirator with multi- purpose combination (US) or type ABEK (EN 14387) respirator cartridges as a backup to engineering controls. If the respirator is the sole means of protection, use a full-face supplied air respirator. Use respirators and components tested and approved under appropriate government standards such as NIOSH (US) or CEN (EU).		ype ABEK (EN ols. If the plied air respirator.
Conditions to avoid	No specific data		
Incompatible materials	No specific data		
Hazardous decomposition products	Under normal conditions of storage products should not be produced.		mposition
Other information	When using, do not eat, drink, or s	smoke. May contain mater	ial of animal origin.

SECTION 9: PHYSICAL AND CHEMICAL PROPERTIES

Information on basic physical and chemical properties

information on basic physical and	chemical pro	opercies
Physical state	:	Liquid
Color	:	Colorless
Odor	:	Not available
Odor threshold	:	Not available
рН	:	≈8.0
Melting point	:	Not available
Boiling point	:	Not available
Flash Point	:	Not available
Burning time	:	Not applicable
Burning rate	:	Not applicable
Evaporation rate	:	Not available
Flammability (solid, gas)	:	Not available
Lower and upper explosive (flammab	le) limits :	Not available
Vapor pressure	:	Not available
Vapor density	:	Not available
Relative density	:	Not available
Solubility	:	Soluble in the following materials: cold water and hot water.
Partition coefficient n-octanol/water	:	Not available
Auto-ignition temperature	:	Not available
Decomposition temperature	:	Not available
SADT	:	Not available
Viscosity	:	Not available
Other information	No additional	information available

SECTION 10: STABILITY AND REACTIVITY

Reactivity	No specific test data related to reactivity available for this product or its ingredients.
Chemical Stability	The product is stable under recommended storage conditions.
Possibility Of Hazardous Reactions	Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions To Avoid	No specific data.
Incompatible Materials	Acids, metals. (Note: Over a period of time, sodium azide may react with copper, lead, brass, or solder in plumbing systems to form an accumulation of HIGHLY EXPLOSIVE compounds of lead azide and copper azide.)

Corporate Offices: 160 Oxmoor Blvd • Birmingham, AL 35209 • USA Mailing Address: P.O. Box 26221 • Birmingham, AL 35260 • USA Tel: 205.945.1774 • U.S. and Canada: 800.722.2255 • Fax: 205.945.8768 Email: info@southernbiotech.com • Website: www.southernbiotech.com

Rev. 27-Aug-21

Goat Fab Anti-Human IgG-AP	SDS No. 2231533	Page 6 of 8
----------------------------	-----------------	-------------

Hazardous Decomposition Products Under normal conditions of storage and use, hazardous decomposition products should not be produced.

SECTION 11: TOXICOLOGICAL INFORMATION

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	
Sodium Azide	LD50 Oral	Mouse	27 mg/kg	
	LD50 Oral	Rat	27 mg/kg	
	LD50 Dermal	Rabbit	20 mg/kg	
Glycerol	LD50 Oral	Rat	12,600 mg/kg	

Conclusion/Summary: To the best of our knowledge, the toxicological properties of this product have not been thoroughly investigated. No data available Skin corrosion/irritation: Serious eye damage/irritation: No data available Respiratory or skin sensitization: No data available Germ cell mutagenicity: No data available Carcinogenicity No data available. This mixture is not listed by NTP, IARC, ACGIH or OSHA as a carcinogen. No data available **Reproductive toxicity: Developmental toxicity:** No data available Specific target organ toxicity (single exposure): No data available Specific target organ toxicity (repeated exposure): No data available Aspiration hazard: No data available **Other Information:** No data available

SECTION 12: ECOLOGICAL INFORMATION

Ecotoxicity

Product / ingredient name	Result	Species	Exposure			
Sodium Azide	Acute EC50 0.348 mg/L Fresh water	Algae – Pseudokirchneriella subcapitata	96 hours			
	Acute EC50 4.2 to 6.2 mg/L Fresh water	Daphnia - Daphnia pulex - Larvae	48 hours			
	Acute LC50 9000 ug/L Fresh water	Crustaceans - Gammarus lacustris	48 hours			
	Acute LC50 0.68 mg/L Fresh water	Fish - Lepomis macrochirus	96 hours			
Persistence and degradability No data available						

No data available
No data available
No data available
No data available
Although present at low concentrations, disposal should consider that sodium azide is present. Releases to the environment should be avoided. Very toxic to aquatic life

SECTION 13: DISPOSAL CONSIDERATIONS

Disposal methods

The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any byproducts should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with

Goat Fab Anti-Human IgG-AP	SDS No. 2231533	Page 7 of 8

jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

SECTION 14: TRANSPORT INFORMATION

	DOT	ΙΑΤΑ	
	Classification		
UN number	Not regulated	Not regulated	
UN proper	Not regulated	Not regulated	
Transport hazard class(es)	Not regulated	Not regulated	
Packing group	Not regulated	Not regulated	

pollutant

Environmental Hazards: Based on the data available, the mixture is not regulated as an environmental hazard or a marine

Special precautions for user: Always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

SECTION 15: REGULATORY INFORMATION

US Federal and State Regulations

SARA section 313	Not listed
SARA section 311/312 Classification	Acute Health Hazard
TSCA status	Not listed
WHMIS classification	Not listed
California Proposition 65	Not listed
Chemical Safety Assessment	Not listed

SARA 302/304

Composition/information on ingredients

Name	%	EHS	SARA 302 TPQ		SARA 304 RQ	
			(lbs)	(gallons)	(lbs)	(gallons)
Sodium Azide	< 0.1	Yes	500	-	1000	-

SARA 304 RQ 1000000 lbs / 454000 kg

State regulations					
New Jersey					
Sodium Azide	26628-22-8				
Sodium Phosphate	7558-79-4				
Massachusetts					
Sodium Azide	26628-22-8				
Sodium Phosphate	7558-79-4				
Pennsylvania					
Sodium Azide	26628-22-8				
Sodium Phosphate	7558-79-4				
Glycerol	56-81-5				
Minnesota					
Sodium Azide	26628-22-8				
Rhode Island					
Sodium Azide	26628-22-8				
Glycerol	56-81-5				

Rev. 27-Aug-21

All components	are	listed	or	exempted.

International regulations

Canada inventory

International listsAustralia inventory (AICS): All components are listed or exempted.
China inventory (IECSC): All components are listed or exempted.
Japan inventory: All components are listed or exempted.
Korea inventory: All components are listed or exempted.
Malaysia Inventory (EHS Register): All components are listed or exempted.
New Zealand Inventory of Chemicals (NZIoC): All components are listed or exempted.
Philippines inventory (PICCS): All components are listed or exempted.
Taiwan inventory (CSNN): All components are listed or exempted.

SECTION 16: OTHER INFORMATION

Indication of changes
Other information

: 27-Aug-21

This document has been prepared in accordance with the SDS requirements of the OSHA Hazard Communication Standard 29 CFR 1910.1200

GHS Full Text Phrases:

H300	Fatal if swallowed
H310	Fatal in contact with skin
H400	Very toxic to aquatic life
H410	Very toxic to aquatic life with long lasting effects

NFPA health hazard	: 1 - May be irritating	
NFPA fire hazard	: 0 - Not combustible	
NFPA reactivity	: 0 - Not reactive when mixed with water	
HMIS III Rating		
Health	: 1 - Slight Hazard - Irritation or minor reversible injury possible	\mathbf{X}
Flammability	: 0 - Minimal Hazard	\sim
Physical	: 0 - Minimal Hazard	

Disclaimer: While SouthernBiotech (d.b.a. Southern Biotechnology Associates, Inc.) believes the information contained herein is valid and accurate, SouthernBiotech makes no warranty or representation as to its validity, accuracy, or currency. SouthernBiotech shall not be liable or otherwise responsible in any way for use of either this information or materials to which it applies. Disposal of Hazardous materials may be subject to local laws or regulations.

SDS US (GHS HazCom) - US Only