SouthernBiotech



SECTION 1: PRODUCT AND COMPANY IDENTIFICATION

GHS Product Identifier	Sheep Anti-Rat IgG(H+L)-HRP
Other means of identification	N/A
Product type	Liquid
Product code	6900-05
Chemical formula	Not applicable
CAS No	Not applicable
SDS No.	2234239
Relevant Identified uses of the substance or mixture and uses	
advised against	Not applicable
Supplier's details	Southern Biotechnology Associates, Inc. 160 Oxmoor Boulevard Birmingham, Alabama 35209 USA Tel: (205) 945-1774 Fax: (205) 945-8768 Website: www.southernbiotech.com
Distributor and Emergency Phone No.	Refer to website for distributor and emergency phone numbers. Tel: (205) 945-1774

SECTION 2: HAZARDS IDENTIFICATION

Classification of the substance or mixture

GHS-US classification

Not a hazardous substance or mixture

Label elements

GHS-US labeling Hazard pictograms (GHS-US) Not a hazardous substance or mixture

Other hazards

none

Unknown acute toxicity (GHS US) Full text of H-phrases: see section 16 No data available

SECTION 3: COMPOSITION/INFORMATION ON INGREDIENTS

Substance/Mixture	Mixture
Other Means of Identification	Not available
CAS Number/other identifiers	
CAS Number	Not applicable

Ingredient Name	Product Identifier	Percent	GHS Classification
Glycerol	(CAS No.) 56-81-5 / [EINECS(EC#)] 200-289-5	50	Not Classified

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section. Occupational exposure limits, if available, are listed in Section 8

Rev. 29-Mar-21

SECTION 4: FIRST-AID MEASURES

Description of first aid measures	
First-aid measures general	Never give anything by mouth to an unconscious person. If you feel unwell, seek medical advice. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.
First-aid measures after eye contact	Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10 minutes. Consult a physician.
First-aid measures after inhalation	Remove victim to fresh air and keep at rest in a position comfortable for breathing. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. Consult a physician.
First-aid measures after skin contact	Flush contaminated skin with plenty of water and soap. Remove contaminated clothing and shoes. Get medical attention if symptoms occur. Wash clothing before reuse. Clean shoes thoroughly before reuse.
First-aid measures after ingestion	Wash out mouth with water. Remove dentures if any. Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention. If necessary, call a poison center.
Most important symptoms and effects, both acute and delayed	See Sections 2 and 11
Indication of any immediate medica	al attention and special treatment needed, if necessary
Notes to physician	Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
Specific treatments	No specific treatment.

Protection of first-aiders

No specific treatment. No action shall be taken involving any personal risk or without suitable training. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation.

SECTION 5: FIRE-FIGHTING MEASURES

Extinguishing media

Suitable extinguishing media	Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide.
Unsuitable extinguishing media	None known
Special hazards arising from the substance or mixture	Carbon oxides, nitrogen oxides (NOx)
Hazardous thermal decomposition products	No specific data
Special protective actions for firefighters	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
Special protective equipment for firefighters	Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode

SECTION 6: ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

Sheep Anti-Rat IgG(H+L)-HRP	SDS No. 2234239	Page 3 of 7
-----------------------------	-----------------	-------------

General measures: This product contains a material of biological origin. Use universal precautions during clean up procedures. Avoid breathing (vapor, mist). Use only in a well-ventilated area. Handle in accordance with good industrial hygiene and safety practice. Use personal protective equipment, see section 8.

For non-emergency personnel

No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Avoid breathing vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.

For emergency responders

If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non- emergency personnel".

Environmental precautions

Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).

Methods and material for containment and cleaning up

Small spill: Stop leak if without risk. Move containers from spill area. Absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Large spill: Stop leak if without risk. Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product.

Reference to other sections

See Section 1 for emergency contact information, Section 13 for waste disposal, and Section 8 for exposure controls and personal protection.

SECTION 7: HANDLING AND STORAGE

Precautions for safe handling

Precautions for safe handling: Put on appropriate personal protective equipment (see Section 8). Do not ingest. Avoid contact with eyes, skin and clothing. Avoid breathing vapor or mist. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse container.

Hygiene measures: Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Conditions for safe storage, including any incompatibilities

Technical measures: Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials. (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. Recommended storage temperature: $2 - 8^{\circ}C$

SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION

Control parameters

SDS No. 2234239 Page 4 of 7

Component	CAS-No.	Value	Control parameters	Basis
Glycerol	56-81-5	TWA	10 mg/m3	USA. OSHA - TABLE Z-1 Limits for Air Contaminants - 1910.1000
		TWA	5 mg/m3	USA. OSHA - TABLE Z-1 Limits for Air Contaminants - 1910.1000
		TWA	10 mg/m3	USA. ACGIH Threshold Limit Values (TLV)
	Remarks	Upper Respiratory Tract irritation		
		See Appendix D - Substances with No Established RELs		
		TWA	5 mg/m3	USA. Occupational Exposure Limits (OSHA) - Table Z-1 Limits for Air Contaminants
		TWA	15 mg/m3	USA. Occupational Exposure Limits (OSHA) - Table Z-1 Limits for Air Contaminants

Exposure controls

Appropriate engineering controls

Environmental exposure controls

Personal protective equipment

airborne contaminants. Handle in accordance with good industrial hygiene and safety practice. Wash hands before breaks and at the end of the workday.

Good general ventilation should be sufficient to control worker exposure to

Do no let product enter drains.

Protective goggles, gloves



Hand protection Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. **Body protection** Impervious clothing. Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. Other skin protection Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. Eye protection Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields. Where risk assessment shows air-purifying respirators are appropriate use a full-Respiratory protection face respirator with multi- purpose combination (US) or type ABEK (EN 14387) respirator cartridges as a backup to engineering controls. If the respirator is the sole means of protection, use a full-face supplied air respirator. Use respirators and components tested and approved under appropriate government standards such as NIOSH (US) or CEN (EU). Conditions to avoid No specific data Incompatible materials No specific data

Rev. 30-Jun-21

Sheep Anti-Rat IgG(H+L)-HRP	SDS No. 2234239	Page 5 of 7

Hazardous decomposition products

Under normal conditions of storage and use, hazardous decomposition products should not be produced. When using, do not eat, drink, or smoke. May contain material of animal origin.

Other information

SECTION 9: PHYSLICAL AND CHEMICAL PROPERTIES

Information on basic physical and chemical properties

	-	•
Appearance		
Physical state	:	Liquid
Color	:	Amber
Odor	:	Not available
Odor threshold	:	Not available
рН	:	Not available
Melting point	:	Not available
Boiling point	:	Not available
Flash Point	:	Not available
Burning time	:	Not applicable
Burning rate	:	Not applicable
Evaporation rate	:	Not available
Flammability (solid, gas)	:	Not available
Lower and upper explosive (flammable)	:	Not available
limits		
Vapor pressure	:	Not available
Vapor density	:	Not available
Relative density	:	Not available
Solubility	:	Soluble in the following materials: cold water and hot water.
Partition coefficient n-octanol/water	:	Not available
Auto-ignition temperature	:	Not available
Decomposition temperature	:	Not available
SADT	:	Not available
Viscosity	:	Not available
Other information		

No additional information available

SECTION 10: STABILITY AND REACTIVITY

Reactivity

No specific test data related to reactivity available for this product or its ingredients. **Chemical Stability** The product is stable. **Possibility Of Hazardous Reactions** Under normal conditions of storage and use, hazardous reactions will not occur. **Conditions To Avoid** No specific data. **Incompatible Materials** Strong oxidizers

Hazardous Decomposition Products No specific data.

SECTION 11: TOXICOLOGICAL INFORMATION

Information on toxicological effects

Acute toxicity No data available Conclusion/Summary: To the best of our knowledge, the toxicological properties of this product have not been thoroughly investigated. No data available Skin corrosion/irritation: Serious eye damage/irritation: No data available

Rev. 30-Jun-21

Sheep Anti-Rat IgG(H+L)-HRP	SDS No. 2234239	Page 6 of 7

Respiratory or skin sensitization: Germ cell mutagenicity: Carcinogenicity	No data available No data available No data available. This mixture is not listed by NTP, IARC, ACGIH or OSHA as a carcinogen.	
Reproductive toxicity:	No data available	
Developmental toxicity:	No data available	
Specific target organ toxicity (single exposure): No data available		
Specific target organ toxicity (repeated exposure): No data available		
Aspiration hazard:	No data available	
Other Information:	No data available	

SECTION 12: ECOLOGICAL INFORMATION

Toxicity	No data available
Persistence and degradability	No data available
Bioaccumulative potential	No data available
Mobility in soil	No data available
Other adverse effects	No data available

SECTION 13: DISPOSAL CONSIDERATIONS

Disposal methods

The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any byproducts should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

SECTION 14: TRANSPORT INFORMATION

	DOT	ΙΑΤΑ
	Classification	
UN number	Not regulated	Not regulated
UN proper	Not regulated	Not regulated
Transport hazard class(es)	Not regulated	Not regulated
Packing group	Not regulated	Not regulated

Special precautions for user: Transport within user s premises always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

SECTION 15: REGULATORY INFORMATION

U.S. Federal regulations

TSCA 8(a) CDR Exempt/Partial exemption: Not determined United States inventory (TSCA 8b): All components are listed or exempted. Clean Water Act (CWA) 311: disodium hydrogenorthophosphate Not listed

California Proposition 65

SARA 302/304

Composition/informationoningredients

SARA 302: No chemicals in this material are subject to the reporting requirements of SARA Title III, Section 302.

Rev. 30-Jun-21

Sheep Anti-Rat IgG(H+L)-HRP	SDS No. 2234239	Page 7 of 7
onoop / and rad igo(in 2) in a	OBO NO. LEO IEGO	I ago I ol I

SARA 313 Components

SARA 313: This material does not contain any chemical components with known CAS numbers that exceed the threshold (De Minimis) reporting levels established by SARA Title III, Section 313 SARA 311/312

Classification	Chronic	health hazard
<u>State regulations</u> New Jersey		
Sodium Phos	ohate	7558-79-4
Massachusetts		
Sodium Phos	ohate	7558-79-4
Pennsylvania		
Sodium Phos	ohate	7558-79-4
Glycerol		56-81-5
Rhode Island		
Glycerol		56-81-5
Canada inventory		All components are listed or exempted.

International regulations

International lists Australia inventory (AICS): All components are listed or exempted. China inventory (IECSC): All components are listed or exempted. Japan inventory: All components are listed or exempted. Korea inventory: All components are listed or exempted. Malaysia Inventory (EHS Register): All components are listed or exempted. New Zealand Inventory of Chemicals (NZIoC): All components are listed or exempted. Philippines inventory (PICCS): All components are listed or exempted. Taiwan inventory (CSNN): All components are listed or exempted.

SECTION 16: OTHER INFORMATION

Indication of changes Other information	 30-Jun-21 This document has been prepared in accordance with the SDS requirements of the OSHA Hazard Communication Standard 29 CFR 1910.1200
NFPA health :	0 - No unusual hazard
NFPA fire hazard :	0 - Not combustible
NFPA reactivity :	0 - Not reactive when mixed with water
HMIS III Rating	
Flammability :	0- Minimal Hazard 0 - Minimal Hazard 0 - Minimal Hazard

While SouthernBiotech (d.b.a. Southern Biotechnology Associates, Inc.) believes the information contained herein is valid and accurate, SouthernBiotech makes no warranty or representation as to its validity, accuracy, or currency. SouthernBiotech shall not be liable or otherwise responsible in any way for use of either this information or materials to which it applies. Disposal of Hazardous materials may be subject to local laws or regulations.

SDS US (GHS HazCom) - US Only